Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

BZ381 NYC PARKS NY LTANKS S105054704
WSW WEST 23RD ST & NEPTUNE AVE N/A

1/2-1 BROOKLYN, NY

0.616 mi.

3253 ft. Site 3 of 5 in cluster BZ

Relative: LTANKS:
Higher Name: NYC PARKS

Actual: Address: WEST 23RD ST & NEPTUNE AVE

 0 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0100863 / 2008-06-13

 Facility ID:
 0100863

 Site ID:
 159580

 Spill Date:
 2001-04-23

 Spill Cause:
 Tank Test Failure

 Spill Source:
 Commercial/Industrial

Spill Class: B3

Cleanup Ceased: Not reported SWIS: 2401
Investigator: JMKRIMGO Referred To: Not reported Reported to Dept: 2001-04-23 CID: 382

Water Affected:

Not reported
Spill Notifier:

Last Inspection:

Recommended Penalty:

Meets Standard:

UST Involvement:

Remediation Phase:

Date Entered In Computer:

Not reported
False
True
False
0

2001-04-23

Spill Record Last Update: 2008-06-13
Spiller Name: ANDRE LAPRE
Spiller Company: NYC PARKS
Spiller Address: Not reported
Spiller County: 001

Spiller Contact: MICHAEL COLLINS
Spiller Phone: (631) 586-4900
Spiller Extention: Not reported

DEC Region: 2 DER Facility ID: 134794

DEC Memo: "6/13/08. J.Krimgold reviewed the Site Assessment Report prepared by

Empire Environmental Services and dated June 24, 2003. Base on the data presented in the report no contaminant concentrations were found above TAGM levels in soil. GW was not encountered and analyzed during investigation as tenk classure. Task (IRS #2.604000) was alread in

investigation or tank closure. Tank (PBS #2-604990) was closed in

place. NFA. JMK. " "ULAGE FAILURE."

Not reported

All TTF:

Remarks:

Cause:

Facility ID: 0100863 Spill Number: 0100863 Spill Tank Test: 1526241 Site ID: 159580 Tank Number: Not reported Tank Size: 1500 Material: 0001 EPA UST: Not reported Not reported UST:

Page: 1

Map ID MAP FINDINGS
Direction

Distance Elevation Site

Site Database(s) EPA ID Number

Source: Not reported

Test Method: 03

Test Method 2: Horner EZ Check I or II

Leak Rate: .00

Gross Fail: Not reported Modified By: Spills Last Modified Date: Not reported

All Materials:

Site ID: 159580 Operable Unit ID: 839712 Operable Unit: 01 Material ID: 560363 Material Code: 0001A Material Name: #2 fuel oil Case No.: Not reported Material FA: Petroleum Quantity: .00 Units: G Recovered: .00

Oxygenate: Not reported

EDR ID Number